





## ***TMT 2000***

### Assembly tables




Assembly table for pre-assembly of hardware and gaskets. Stable steel construction. Work table for all pre-assembly tasks for hardware and gaskets on windows and doors. Equipped with two clamps. Clamping device for profiles with a depth of 45 - 120 mm and facing width of 50 - 150 mm. Clamping position can be adjusted. Clamping cylinder is activated by a foot switch. 180° pivoting feature for the clamped profiles in 30° steps via a foot switch, lockable. Support arms for long parts. Two storage areas for setting down tools and small parts. Drawers for tools. Rack for screw driving unit or drill. 4-fold compressed air supply. Double two-pin grounded socket.




### Clamping device

Clamping device for profiles with a depth of 45 - 120 mm and facing width of 50 - 150 mm. Clamping position adjustable in the longitudinal direction of the profile, clamping cylinder actuated via a foot switch




### Pivoting mechanism

180° pivoting feature for the clamped profiles in 30° steps via a foot switch, lockable




### Support arms

Support arms for long parts such as multiple locking hardware. Storage areas for tools and small parts




### Storage area

Storage area with 5 plastic trays for small accessories, hardware and screws




### Drawer

Drawer for tools. Rubber coated tool trays




### Maintenance unit

Maintenance unit for compressed-air tools




### 4-fold compressed air connection

4-fold compressed air connection for connecting compressed-air tools



### Articulated foot

Working height can be set to 850 – 1.000 mm by means of adjustable feet



### Tool rack

Tool rack for pneumatic or electric tools

**TMT 2000 / ASSEMBLY TABLES****DIMENSION AND WEIGHT**

|             |       |
|-------------|-------|
| Length (mm) | 2.000 |
| Width (mm)  | 850   |
| Height (mm) | 1.970 |
| Weight (kg) | 145   |

**CHARACTERISTICS**

|                                                      |    |
|------------------------------------------------------|----|
| Clamps                                               | 2  |
| Storage areas for setting down tools and small parts | 2  |
| Drawers for tools                                    | ●  |
| Rack for screw driving unit or drill                 | ●  |
| 4-fold compressed air supply                         | ●  |
| Operating air pressure (bar)                         | 7  |
| Air consumption approx. (l/min)                      | 20 |
| Double two-pin grounded socket                       | ●  |

Included ● Available ○